DART AEROSPACE LTD Work Orde			24729			
Description: Part Vest Part Numbe			Darf Number	867-43001-16		
Part Numbe			Part Number:	PER	7-4300	05-1 -28c-
Dwg: Qt			Qty:		1/1	
Ļ				1	Page of	·
Step 1	Location	Procedure Issue Traveler		Ву	Date	Qty
- 1	76	USE PARTS B67-43001-	261 B 240h;	M	05 1114	1/
		And - 285 B 239B4 for 4	est paint	177		
		of lock much senset on are	0.00.			
2	FP	SANCHANCE I dentify, SANCE	Cl Analysis Simila	M	0511/4	1/
	•	Areas on parts - 261 % -	285	X "'''	0) ., / 1	//
:3	FP	Powclar cont Red As per	_	W	05/11/4	1
-LIA	Qc3/5	Inspect Power unt i pu		7		1
		Inspection of proper Adhesian	(us·12·07	/1
5	Ac	(cs-1;				
		close w/o				
	Nerweel	COSE W/O	-			
			7			
		both soncled and unspect	ed Avens			" * <u></u>
		had solice adhesion		· · · · · · · · · · · · · · · · · · ·		
46	Qc_	Colomantine parts.		4	5-12.07	1/1
						
Rev	Date	Change	Revis	L		